Map ID MAP FINDINGS

Direction Distance

Distance Elevation Site EDR ID Number Database(s) EPA ID Number

 1431
 SPILL NUMBER 0011887
 NY LTANKS
 S104950588

 North
 1668 WEST 6TH ST
 NY Spills
 N/A

> 1 1.804 mi. 9525 ft. BROOKLYN, NY

SWIS:

 Relative:
 LTANKS:

 Higher
 Name:
 SPILL NUMBER 0011887

 Actual:
 Address:
 1668 WEST 6TH ST

 18 ft.
 City,State,Zip:
 BROOKLYN, NY

 Spill Number/Closed Date:
 0011887 / 2003-10-22

 Facility ID:
 0011887

 Site ID:
 232080

 Spill Date:
 2001-02-03

 Spill Cause:
 Tank Failure

 Spill Source:
 Private Dwelling

Spill Class: B3

Cleanup Ceased: Not reported

2401

Investigator: JMKRIMGO
Referred To: Not reported
Reported to Dept: 2001-02-03
CID: 281
Water Affected: Not reported
Spill Notifier: Fire Department
Last Inspection: Not reported
Recommended Penalty: False

Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2001-

Date Entered In Computer: 2001-02-03

Spill Record Last Update: 2003-10-22

Spiller Name: Not reported

Spiller Company: UNKNOWN

Spiller Address: Not reported

Spiller County: 999

Spiller Contact: BROOKLYN FIRE DEPT

Spiller Phone: (718) 965-8261 Spiller Extention: Not reported

DEC Region: 2 DER Facility ID: 191255

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was

KRIMGOLD 2/3/01. RP hired AL Eastman to do the cleanup. PBS #2-281859. JK. 2/26/03. J. Krimgold at site. Cleanup has been

completed. Pending Non-Haz. Mat. Manifest. "

Remarks: "FIRE DEPT RESPONDED TO ABOVE LOCATION FOR REPORT OF ABOVE MATERIAL

BEING SPILLED. UPON FURTHER INVESTIGATION A LEAK IN TANK HAS BEEN DISCOVERED. FIRE DEPT ON SCENE AND HAZMAT UNIT IS RESPONDING. NYC

FIRE DEPT IS REQUESTING CALL BACK FROM DEC."

All Materials:

232080 Site ID: Operable Unit ID: 833782 Operable Unit: 01 542177 Material ID: Material Code: 0001A Material Name: #2 fuel oil Case No.: Not reported Material FA: Petroleum Quantity: 20.00

Map ID MAP FINDINGS

Direction Distance Elevation

tance EDR ID Number vation Site Database(s) EPA ID Number

Units: G Recovered: .00

Oxygenate: Not reported

 Name:
 RESIDENCE - MULTI

 Address:
 1668 WEST 6TH ST

 City,State,Zip:
 BROOKLYN, NY

 Spill Number/Closed Date:
 0011889 / 2003-10-22

 Facility ID:
 0011889

 Site ID:
 232081

 Spill Date:
 2001-02-03

 Spill Cause:
 Tank Overfill

 Spill Source:
 Private Dwelling

Spill Class: C3

Cleanup Ceased: Not reported

 SWIS:
 2401

 Investigator:
 JMKRIMGO

 Referred To:
 Not reported

 Reported to Dept:
 2001-02-03

 CID:
 398

Water Affected:
Spill Notifier:
Fire Department
Last Inspection:
Recommended Penalty:
Meets Standard:
UST Involvement:
Remediation Phase:
Not reported
False
Palse
False
False
0

Date Entered In Computer: 2001-02-03

Spill Record Last Update: 2003-10-22

Spiller Name: Not reported

Spiller Company: UNKNOWN

Spiller Address: Not reported

Spiller County: 999

Spiller Contact: FIREFIGHTER HACK
Spiller Phone: (917) 769-0483
Spiller Extention: Not reported
DEC Region: 2

DEC Region: 2
DER Facility ID: 191255

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was

KRIMGOLD "

Remarks: "CALLER STATES OVERFILL. MOST RECOVERED. NO CALL BACK REQUESTED.

Also, see spill # 0011887."

All Materials:

Site ID: 232081 Operable Unit ID: 833786 Operable Unit: 01 Material ID: 542179 Material Code: 0001A #2 fuel oil Material Name: Case No.: Not reported Petroleum Material FA: Quantity: 50.00 Units: G Recovered: .00

Oxygenate: Not reported

Map ID MAP FINDINGS

Direction Distance Elevation

EDR ID Number Database(s) EPA ID Number Site

SPILLS:

Name: APARTMENT BLDG 1668 WEST 6TH ST Address: City, State, Zip: BROOKLYN, NY Spill Number/Closed Date: 0011900 / 2002-05-20

Facility ID: 0011900 Facility Type: ER DER Facility ID: 191255 Site ID: 137583 DEC Region: Spill Cause: Unknown Spill Class: C3 SWIS: 2401 Spill Date: 2001-02-03 Investigator: **JMKRIMGO** Referred To: Not reported Reported to Dept: 2001-02-03 CID: 390

Water Affected: Not reported Private Dwelling Spill Source: Spill Notifier: Local Agency Cleanup Ceased: Not reported Cleanup Meets Std: False Last Inspection: Not reported Recommended Penalty: False **UST Trust**: False Remediation Phase:

Date Entered In Computer: 2001-02-03 Spill Record Last Update: 2003-10-22 Spiller Name: **MEHMET**

Spiller Company: APARTMENT BLDG -Spiller Address: 1668 W 6TH ST Spiller Company: 001 Contact Name: **MEHMET**

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was

KRIMGOLD "

Remarks: "tank ahas leaked to a concrete shell - approx 30-40 gals - clen up

in progress. Same as 0011887 and 0011889."

All Materials:

137583 Site ID: Operable Unit ID: 833800 Operable Unit: 01 Material ID: 542190 Material Code: 0001A Material Name: #2 fuel oil Case No.: Not reported Petroleum Material FA: Quantity: 40.00 Units: G .00 Recovered:

Oxygenate: Not reported